

IAMU OQ Past Due And Expired Training Report

Whittemore Municipal Utilities

Mike Elbert Operator Whittemore

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
4.13 Excavation safety	7/11/2001	2/12/2010	4/27/2011	4/27/2012	Past Due
Requalification Requirement 1					
Module 404		4/27/2011	Taught By IAMU		
Or Hands On 4.13 Excavation safety					
7.11 Plastic pipe joining (fusion)					Not Taken
Original Requirement 1					
Hands On 7.11 Plastic pipe joining (fusion)					
7.20 Tapping and stopping steel pipe 1" through 4"	9/23/2004	9/23/2004	9/16/2008	9/16/2011	Expired
Original Requirement 1					
Hands On 7.20 Tapping and stopping steel pipe 1" through 4"		9/16/2008	Taught By IAMU		
9.1 Metering	7/11/2001	7/11/2001	9/14/2006	9/14/2011	Expired
Original Requirement 1					
Hands On 9.1 Metering		9/14/2006	Taught By IAMU		

Bryan Meyer Operator Whittemore

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
4.13 Excavation safety	6/26/2002	1/29/2010	4/20/2011	4/20/2012	Past Due
Requalification Requirement 1					
Module 404		4/20/2011	Taught By IAMU		
Or Hands On 4.13 Excavation safety					
7.11 Plastic pipe joining (fusion)					Not Taken
Original Requirement 1					
Hands On 7.11 Plastic pipe joining (fusion)					
7.20 Tapping and stopping steel pipe 1" through 4"	9/11/2002	9/12/2007	9/16/2008	9/16/2011	Expired
Original Requirement 1					
Hands On 7.20 Tapping and stopping steel pipe 1" through 4"		9/16/2008	Taught By IAMU		
7.22 Tapping and stopping polyethylene pipe	5/7/2002	9/11/2002	5/8/2007	5/8/2012	Expired
Original Requirement 1					
Hands On 7.22 Tapping and stopping polyethylene pipe		5/8/2007	Taught By IAMU		
9.1 Metering	4/19/2002	9/10/2004	5/10/2007	5/10/2012	Expired
Original Requirement 1					
Hands On 9.1 Metering		5/10/2007	Taught By IAMU		