

IAMU OQ Past Due And Expired Training Report

Bedford Municipal Gas Co.

C. Leroy Dukes Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
2.3 System up-rating					Not Taken
Original Requirement 1					
Module 521					
2.4 Investigating and documenting line failure					Not Taken
Original Requirement 1					
Module 462					
4.1 Personal protective equipment					Not Taken
Original Requirement 1					
Module 111					
4.12 Abandoning facilities					Not Taken
Original Requirement 1					
Module 471					
4.2 Power tool safety					Not Taken
Original Requirement 1					
Module 121					
4.3 Proper firefighting techniques					Not Taken
Original Requirement 1					
Module 122					
4.9 Job site protection					Not Taken
Original Requirement 1					
Module 401					
6.4 Pilot light operation					Not Taken
Original Requirement 1					
Module 311					
Original Requirement 2					
Module 324					
7.10 Reinforcing steel and plastic mains					Not Taken
Original Requirement 1					
Module 463					
7.12 Plastic pipe joining (mechanical couplings)					Not Taken
Original Requirement 1					
Hands On 7.12 Plastic pipe joining (mechanical couplings)					
7.13 Recognition of defective material					Not Taken
Original Requirement 1					
Module 411					
Original Requirement 2					
Module 412	7/25/2011			Taught By IAMU	
Original Requirement 3					
Module 421	7/25/2011			Taught By IAMU	

C. Leroy Dukes Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
7.16 Damage prevention					Not Taken
Original Requirement 1					
Module 462					
7.18 Replacing emergency valves					Not Taken
Original Requirement 1					
Module 441		7/25/2011	Taught By IAMU		
Original Requirement 2					
Module 511					
Or Hands On 12.3 Inspecting and maintaining key valves					
7.2 Procedures for abandoning facilities					Not Taken
Original Requirement 1					
Module 471					
7.20 Tapping and stopping steel pipe 1" through 4"					Not Taken
Original Requirement 1					
Hands On 7.20 Tapping and stopping steel pipe 1" through 4"					
7.22 Tapping and stopping polyethylene pipe					Not Taken
Original Requirement 1					
Hands On 7.22 Tapping and stopping polyethylene pipe					
7.8 Steel and cast iron repair fittings					Not Taken
Original Requirement 1					
Module 461					
Original Requirement 2					
Hands On 7.8 Steel and cast iron repair fittings					
7.9 Maintaining steel and cast iron mains					Not Taken
Original Requirement 1					
Module 462					
8.3 Operating boring equipment					Not Taken
Original Requirement 1					
Hands On 8.3 Operating boring equipment					
10.6 Holiday detection (coating inspection)					Not Taken
Original Requirement 1					
Module 431		4/6/2012	Taught By IAMU		
Original Requirement 2					
Hands On 10.6 Holiday detection (coating inspection)					
12.1 Operating valves (including emergency valves), regulators, and					Not Taken
Original Requirement 1					
Module 244					
Original Requirement 2					
Module 511					
Original Requirement 3					
Module 512					

Bedford Municipal Gas Co.

C. Leroy Duker Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
12.2 Inspecting pressure regulating and limiting stations					Not Taken
Original Requirement 1 Module 512					
Or Hands On 12.2 Inspecting pressure regulating and limiting stations					
12.3 Inspecting and maintaining key valves					Not Taken
Original Requirement 1 Module 511					
Or Hands On 12.3 Inspecting and maintaining key valves					
12.4 System uprating					Not Taken
Original Requirement 1 Module 521					

Joe Pace Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
2.1 Documenting materials and installation records					Not Taken
Original Requirement 1 Module 402					
2.2 Documenting maximum allowable operating pressure (MAOP)					Not Taken
Original Requirement 1 Module 421					
2.3 System up-rating					Not Taken
Original Requirement 1 Module 521					
2.4 Investigating and documenting line failure					Not Taken
Original Requirement 1 Module 462					
3.1 Locating facilities using the conductive method					Not Taken
Original Requirement 1 Module 402					
Original Requirement 2 Hands On 3.1 Locating facilities using the conductive method					
3.2 Locating facilities using the inductive method					Not Taken
Original Requirement 1 Module 402					
Original Requirement 2 Hands On 3.2 Locating facilities using the inductive method					

Joe Pace Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
3.3 Locating facilities using the inductive method (two persons)					Not Taken
Original Requirement 1					
Module 402					
Original Requirement 2					
Hands On 3.3 Locating facilities using the inductive method (two persons)					
3.4 Determining depth through triangulation					Not Taken
Original Requirement 1					
Module 402					
Original Requirement 2					
Hands On 3.4 Determining depth through triangulation					
3.5 System mapping					Not Taken
Original Requirement 1					
Module 402					
4.1 Personal protective equipment					Not Taken
Original Requirement 1					
Module 111					
4.10 Purging safety					Not Taken
Original Requirement 1					
Module 422					
4.11 Pressure testing steel and plastic pipeline					Not Taken
Original Requirement 1					
Module 421					
4.12 Abandoning facilities					Not Taken
Original Requirement 1					
Module 471					
4.13 Excavation safety					Not Taken
Original Requirement 1					
Module 404					
4.2 Power tool safety					Not Taken
Original Requirement 1					
Module 121					
4.3 Proper firefighting techniques					Not Taken
Original Requirement 1					
Module 122					
4.4 Controlling the accidental release of gas					Not Taken
Original Requirement 1					
Module 131					
4.9 Job site protection					Not Taken
Original Requirement 1					
Module 401					

Bedford Municipal Gas Co.

Joe Pace Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
5.5 Flame ionization					Not Taken
Original Requirement 1					
Module 232					
Or Hands On 5.5 Flame ionization					
6.4 Pilot light operation					Not Taken
Original Requirement 1					
Module 311		2/7/2007	Taught By IAMU		
Original Requirement 2					
Module 324					
7.1 Pressure testing steel and plastic pipeline					Not Taken
Original Requirement 1					
Module 421					
7.10 Reinforcing steel and plastic mains					Not Taken
Original Requirement 1					
Module 463					
7.12 Plastic pipe joining (mechanical couplings)					Not Taken
Original Requirement 1					
Hands On 7.12 Plastic pipe joining (mechanical couplings)					
7.13 Recognition of defective material					Not Taken
Original Requirement 1					
Module 411					
Original Requirement 2					
Module 412					
Original Requirement 3					
Module 421					
7.15 Steel pipe joining by mechanical couplings					Not Taken
Original Requirement 1					
Module 412					
Original Requirement 2					
Hands On 7.15 Steel pipe joining by mechanical couplings					
7.16 Damage prevention					Not Taken
Original Requirement 1					
Module 462					
7.17 Application of padding and shielding					Not Taken
Original Requirement 1					
Module 453					
7.18 Replacing emergency valves					Not Taken
Original Requirement 1					
Module 441					
Original Requirement 2					
Module 511					
Or Hands On 12.3 Inspecting and maintaining key valves					

Joe Pace Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
7.19 Installing meter sets					Not Taken
Original Requirement 1 Module 211		2/17/2010	Taught By IAMU		
Original Requirement 2 Module 322		1/12/2012	Taught By IAMU		
Original Requirement 3 Module 452					
7.2 Procedures for abandoning facilities					Not Taken
Original Requirement 1 Module 471					
7.20 Tapping and stopping steel pipe 1" through 4"					Not Taken
Original Requirement 1 Hands On 7.20 Tapping and stopping steel pipe 1" through 4"					
7.22 Tapping and stopping polyethylene pipe					Not Taken
Original Requirement 1 Hands On 7.22 Tapping and stopping polyethylene pipe					
7.3 Cathodic protection (general)					Not Taken
Original Requirement 1 Module 431					
7.4 Constructing facilities across streets, railroads, and waterways					Not Taken
Original Requirement 1 Module 453					
7.5 Operating thermite welder					Not Taken
Module 431 Original Requirement 2 Hands On 7.5 Operating thermite welder					
7.6 Installing tracer wire					Not Taken
Original Requirement 1 Module 451 Original Requirement 2 Module 452					
7.7 Installing valves					Not Taken
Original Requirement 1 Module 451					
7.8 Steel and cast iron repair fittings					Not Taken
Original Requirement 1 Module 461 Original Requirement 2 Hands On 7.8 Steel and cast iron repair fittings					
7.9 Maintaining steel and cast iron mains					Not Taken
Original Requirement 1 Module 462					

Joe Pace Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
8.1 Operating backhoe					Not Taken
Original Requirement 1					
Module 403					
Original Requirement 2					
Hands On 8.1 Operating backhoe					
8.2 Operating trencher					Not Taken
Original Requirement 1					
Hands On 8.2 Operating trencher					
8.3 Operating boring equipment					Not Taken
Original Requirement 1					
Hands On 8.3 Operating boring equipment					
8.4 Ditch and backfill inspection					Not Taken
Original Requirement 1					
Module 404					
10.10 Inspection, monitoring cathodic protection system					Not Taken
Original Requirement 1					
Module 431					
10.1 Cathodic protection					Not Taken
Original Requirement 1					
Module 431					
10.2 Internal corrosion					Not Taken
Original Requirement 1					
Module 431					
10.3 External corrosion					Not Taken
Original Requirement 1					
Module 431					
10.5 Coatings					Not Taken
Original Requirement 1					
Module 431					
10.6 Holiday detection (coating inspection)					Not Taken
Original Requirement 1					
Module 431					
Original Requirement 2					
Hands On 10.6 Holiday detection (coating inspection)					
10.7 Painting and jacketing above ground facilities					Not Taken
Original Requirement 1					
Hands On 10.7 Painting and jacketing above ground facilities					
10.8 Installation of cathodic protection (sacrificial anode system)					Not Taken
Original Requirement 1					
Module 431					

Bedford Municipal Gas Co.

Joe Pace Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
11.3 Testing odorant level					Not Taken
Original Requirement 1					
Module 251		1/12/2012	Taught By IAMU		
Original Requirement 2					
Hands On 11.3 Testing odorant level					
12.1 Operating valves (including emergency valves), regulators, and					Not Taken
Original Requirement 1					
Module 244		1/30/2007	Taught By IAMU		
Original Requirement 2					
Module 511					
Original Requirement 3					
Module 512					
12.2 Inspecting pressure regulating and limiting stations					Not Taken
Original Requirement 1					
Module 512					
Or Hands On 12.2 Inspecting pressure regulating and limiting stations					
12.3 Inspecting and maintaining key valves					Not Taken
Original Requirement 1					
Module 511					
Or Hands On 12.3 Inspecting and maintaining key valves					
12.4 System uprating					Not Taken
Original Requirement 1					
Module 521					

Chuck Quick Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
6.4 Pilot light operation					Not Taken
Original Requirement 1					
Module 311		11/18/2010	Taught By IAMU		
Original Requirement 2					
Module 324					
7.15 Steel pipe joining by mechanical couplings					Not Taken
Original Requirement 1					
Module 412		1/5/2011	Taught By IAMU		
Original Requirement 2					
Hands On 7.15 Steel pipe joining by mechanical couplings					
7.22 Tapping and stopping polyethylene pipe					Not Taken
Original Requirement 1					
Hands On 7.22 Tapping and stopping polyethylene pipe					

Bedford Municipal Gas Co.

Chuck Quick Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
7.8 Steel and cast iron repair fittings					Not Taken
Original Requirement 1					
Module 461		1/19/2011	Taught By IAMU		
Original Requirement 2					
Hands On 7.8 Steel and cast iron repair fittings					
8.3 Operating boring equipment					Not Taken
Original Requirement 1					
Hands On 8.3 Operating boring equipment					
10.6 Holiday detection (coating inspection)					Not Taken
Original Requirement 1					
Module 431		9/8/2011	Taught By IAMU		
Original Requirement 2					
Hands On 10.6 Holiday detection (coating inspection)					

Ernie Saylor Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
2.1 Documenting materials and installation records					Not Taken
Original Requirement 1					
Module 402					
2.2 Documenting maximum allowable operating pressure (MAOP)					Not Taken
Original Requirement 1					
Module 421					
2.3 System up-rating					Not Taken
Original Requirement 1					
Module 521					
2.4 Investigating and documenting line failure					Not Taken
Original Requirement 1					
Module 462					
3.1 Locating facilities using the conductive method					Not Taken
Original Requirement 1					
Module 402					
Original Requirement 2					
Hands On 3.1 Locating facilities using the conductive method					
3.2 Locating facilities using the inductive method					Not Taken
Original Requirement 1					
Module 402					
Original Requirement 2					
Hands On 3.2 Locating facilities using the inductive method					

Bedford Municipal Gas Co.

Ernie Saylor Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
3.3 Locating facilities using the inductive method (two persons)					Not Taken
Original Requirement 1					
Module 402					
Original Requirement 2					
Hands On 3.3 Locating facilities using the inductive method (two persons)					
3.4 Determining depth through triangulation					Not Taken
Original Requirement 1					
Module 402					
Original Requirement 2					
Hands On 3.4 Determining depth through triangulation					
3.5 System mapping					Not Taken
Original Requirement 1					
Module 402					
4.10 Purging safety					Not Taken
Original Requirement 1					
Module 422					
4.1 Personal protective equipment					Not Taken
Original Requirement 1					
Module 111					
4.11 Pressure testing steel and plastic pipeline					Not Taken
Original Requirement 1					
Module 421					
4.12 Abandoning facilities					Not Taken
Original Requirement 1					
Module 471					
4.13 Excavation safety					Not Taken
Original Requirement 1					
Module 404					
4.2 Power tool safety					Not Taken
Original Requirement 1					
Module 121					
4.3 Proper firefighting techniques					Not Taken
Original Requirement 1					
Module 122					
4.4 Controlling the accidental release of gas					Not Taken
Original Requirement 1					
Module 131					
4.9 Job site protection					Not Taken
Original Requirement 1					
Module 401					

Bedford Municipal Gas Co.

Ernie Saylor Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
5.5 Flame ionization					Not Taken
Original Requirement 1					
Module 232					
Or Hands On 5.5 Flame ionization					
6.4 Pilot light operation					Not Taken
Original Requirement 1					
Module 311		2/5/2007	Taught By IAMU		
Original Requirement 2					
Module 324					
7.1 Pressure testing steel and plastic pipeline					Not Taken
Original Requirement 1					
Module 421					
7.10 Reinforcing steel and plastic mains					Not Taken
Original Requirement 1					
Module 463					
7.12 Plastic pipe joining (mechanical couplings)					Not Taken
Original Requirement 1					
Hands On 7.12 Plastic pipe joining (mechanical couplings)					
7.13 Recognition of defective material					Not Taken
Original Requirement 1					
Module 411					
Original Requirement 2					
Module 412					
Original Requirement 3					
Module 421					
7.15 Steel pipe joining by mechanical couplings					Not Taken
Original Requirement 1					
Module 412					
Original Requirement 2					
Hands On 7.15 Steel pipe joining by mechanical couplings					
7.16 Damage prevention					Not Taken
Original Requirement 1					
Module 462					
7.17 Application of padding and shielding					Not Taken
Original Requirement 1					
Module 453					
7.18 Replacing emergency valves					Not Taken
Original Requirement 1					
Module 441					
Original Requirement 2					
Module 511					
Or Hands On 12.3 Inspecting and maintaining key valves					

Bedford Municipal Gas Co.

Ernie Saylor Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
7.19 Installing meter sets					Not Taken
Original Requirement 1 Module 211		2/17/2010	Taught By IAMU		
Original Requirement 2 Module 322		1/12/2012	Taught By IAMU		
Original Requirement 3 Module 452					
7.20 Tapping and stopping steel pipe 1" through 4"					Not Taken
Original Requirement 1 Hands On 7.20 Tapping and stopping steel pipe 1" through 4"					
7.2 Procedures for abandoning facilities					Not Taken
Original Requirement 1 Module 471					
7.22 Tapping and stopping polyethylene pipe					Not Taken
Original Requirement 1 Hands On 7.22 Tapping and stopping polyethylene pipe					
7.3 Cathodic protection (general)					Not Taken
Original Requirement 1 Module 431					
7.4 Constructing facilities across streets, railroads, and waterways					Not Taken
Original Requirement 1 Module 453					
7.5 Operating thermite welder					Not Taken
Module 431 Original Requirement 2 Hands On 7.5 Operating thermite welder					
7.6 Installing tracer wire					Not Taken
Original Requirement 1 Module 451 Original Requirement 2 Module 452					
7.7 Installing valves					Not Taken
Original Requirement 1 Module 451					
7.8 Steel and cast iron repair fittings					Not Taken
Original Requirement 1 Module 461 Original Requirement 2 Hands On 7.8 Steel and cast iron repair fittings					
7.9 Maintaining steel and cast iron mains					Not Taken
Original Requirement 1 Module 462					

Bedford Municipal Gas Co.

Ernie Saylor Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
8.3 Operating boring equipment					Not Taken
Original Requirement 1					
Hands On 8.3 Operating boring equipment					
8.4 Ditch and backfill inspection					Not Taken
Original Requirement 1					
Module 404					
10.1 Cathodic protection					Not Taken
Original Requirement 1					
Module 431					
10.10 Inspection, monitoring cathodic protection system					Not Taken
Original Requirement 1					
Module 431					
10.2 Internal corrosion					Not Taken
Original Requirement 1					
Module 431					
10.3 External corrosion					Not Taken
Original Requirement 1					
Module 431					
10.5 Coatings					Not Taken
Original Requirement 1					
Module 431					
10.6 Holiday detection (coating inspection)					Not Taken
Original Requirement 1					
Module 431					
Original Requirement 2					
Hands On 10.6 Holiday detection (coating inspection)					
10.7 Painting and jacketing above ground facilities					Not Taken
Original Requirement 1					
Hands On 10.7 Painting and jacketing above ground facilities					
10.8 Installation of cathodic protection (sacrificial anode system)					Not Taken
Original Requirement 1					
Module 431					
11.3 Testing odorant level					Not Taken
Original Requirement 1					
Module 251		1/12/2012	Taught By IAMU		
Original Requirement 2					
Hands On 11.3 Testing odorant level					

Bedford Municipal Gas Co.

Ernie Saylor Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
12.1 Operating valves (including emergency valves), regulators, and					Not Taken
Original Requirement 1 Module 244		1/30/2007	Taught By IAMU		
Original Requirement 2 Module 511					
Original Requirement 3 Module 512					
12.2 Inspecting pressure regulating and limiting stations					Not Taken
Original Requirement 1 Module 512					
Or Hands On 12.2 Inspecting pressure regulating and limiting stations					
12.3 Inspecting and maintaining key valves					Not Taken
Original Requirement 1 Module 511					
Or Hands On 12.3 Inspecting and maintaining key valves					
12.4 System uprating					Not Taken
Original Requirement 1 Module 521					

Jeff Scott Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
2.3 System up-rating					Not Taken
Original Requirement 1 Module 521					
2.4 Investigating and documenting line failure					Not Taken
Original Requirement 1 Module 462					
3.2 Locating facilities using the inductive method					Not Taken
Original Requirement 1 Module 402		7/30/2008	Taught By IAMU		
Original Requirement 2 Hands On 3.2 Locating facilities using the inductive method					
3.3 Locating facilities using the inductive method (two persons)					Not Taken
Original Requirement 1 Module 402		7/30/2008	Taught By IAMU		
Original Requirement 2 Hands On 3.3 Locating facilities using the inductive method (two persons)					

Bedford Municipal Gas Co.

Jeff Scott Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
3.4 Determining depth through triangulation					Not Taken
Original Requirement 1					
Module 402		7/30/2008	Taught By IAMU		
Original Requirement 2					
Hands On 3.4 Determining depth through triangulation					
4.1 Personal protective equipment					Not Taken
Original Requirement 1					
Module 111					
4.12 Abandoning facilities					Not Taken
Original Requirement 1					
Module 471					
4.2 Power tool safety					Not Taken
Original Requirement 1					
Module 121					
4.3 Proper firefighting techniques					Not Taken
Original Requirement 1					
Module 122					
4.4 Controlling the accidental release of gas					Not Taken
Original Requirement 1					
Module 131					
4.9 Job site protection					Not Taken
Original Requirement 1					
Module 401					
5.5 Flame ionization					Not Taken
Original Requirement 1					
Module 232					
Or Hands On 5.5 Flame ionization					
6.4 Pilot light operation					Not Taken
Original Requirement 1					
Module 311		2/5/2007	Taught By IAMU		
Original Requirement 2					
Module 324					
7.10 Reinforcing steel and plastic mains					Not Taken
Original Requirement 1					
Module 463					
7.12 Plastic pipe joining (mechanical couplings)					Not Taken
Original Requirement 1					
Hands On 7.12 Plastic pipe joining (mechanical couplings)					

Bedford Municipal Gas Co.

Jeff Scott Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
7.13 Recognition of defective material					Not Taken
Original Requirement 1 Module 411					
Original Requirement 2 Module 412		7/25/2011	Taught By IAMU		
Original Requirement 3 Module 421		7/25/2011	Taught By IAMU		
7.16 Damage prevention					Not Taken
Original Requirement 1 Module 462					
7.18 Replacing emergency valves					Not Taken
Original Requirement 1 Module 441		7/25/2011	Taught By IAMU		
Original Requirement 2 Module 511 Or Hands On 12.3 Inspecting and maintaining key valves					
7.2 Procedures for abandoning facilities					Not Taken
Original Requirement 1 Module 471					
7.20 Tapping and stopping steel pipe 1" through 4"	7/30/2008		7/30/2008	7/30/2011	Expired
Original Requirement 1 Hands On 7.20 Tapping and stopping steel pipe 1" through 4"		7/30/2008	Taught By IAMU		
7.22 Tapping and stopping polyethylene pipe					Not Taken
Original Requirement 1 Hands On 7.22 Tapping and stopping polyethylene pipe					
7.8 Steel and cast iron repair fittings					Not Taken
Original Requirement 1 Module 461					
Original Requirement 2 Hands On 7.8 Steel and cast iron repair fittings					
7.9 Maintaining steel and cast iron mains					Not Taken
Original Requirement 1 Module 462					
8.3 Operating boring equipment	7/30/2008		7/30/2008	7/30/2011	Expired
Original Requirement 1 Hands On 8.3 Operating boring equipment		7/30/2008	Taught By IAMU		
10.6 Holiday detection (coating inspection)					Not Taken
Original Requirement 1 Module 431		7/25/2011	Taught By IAMU		
Original Requirement 2 Hands On 10.6 Holiday detection (coating inspection)					

Bedford Municipal Gas Co.

Jeff Scott Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
11.3 Testing odorant level					Not Taken
Original Requirement 1 Module 251		1/12/2012	Taught By IAMU		
Original Requirement 2 Hands On 11.3 Testing odorant level					
12.1 Operating valves (including emergency valves), regulators, and					Not Taken
Original Requirement 1 Module 244		1/30/2007	Taught By IAMU		
Original Requirement 2 Module 511					
Original Requirement 3 Module 512					
12.2 Inspecting pressure regulating and limiting stations					Not Taken
Original Requirement 1 Module 512 Or Hands On 12.2 Inspecting pressure regulating and limiting stations					
12.3 Inspecting and maintaining key valves					Not Taken
Original Requirement 1 Module 511 Or Hands On 12.3 Inspecting and maintaining key valves					
12.4 System uprating					Not Taken
Original Requirement 1 Module 521					

Kenny Spencer On Call / Welder Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
7.14 Steel pipe joining by welding	3/8/2002	7/24/2006	3/22/2007	3/22/2008	Expired
Original Requirement 1 Hands On 7.14 Steel pipe joining by welding		3/22/2007	Taught By IAMU		

Jeremy Supinger Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
2.3 System up-rating					Not Taken
Original Requirement 1 Module 521					
2.4 Investigating and documenting line failure					Not Taken
Original Requirement 1 Module 462					
3.2 Locating facilities using the inductive method					Not Taken
Original Requirement 1 Module 402		7/30/2008	Taught By IAMU		
Original Requirement 2 Hands On 3.2 Locating facilities using the inductive method					

Bedford Municipal Gas Co.

Jeremy Supinger Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
3.3 Locating facilities using the inductive method (two persons)					Not Taken
Original Requirement 1					
Module 402		7/30/2008	Taught By IAMU		
Original Requirement 2					
Hands On 3.3 Locating facilities using the inductive method (two persons)					
3.4 Determining depth through triangulation					Not Taken
Original Requirement 1					
Module 402		7/30/2008	Taught By IAMU		
Original Requirement 2					
Hands On 3.4 Determining depth through triangulation					
4.1 Personal protective equipment					Not Taken
Original Requirement 1					
Module 111					
4.12 Abandoning facilities					Not Taken
Original Requirement 1					
Module 471					
4.2 Power tool safety					Not Taken
Original Requirement 1					
Module 121					
4.3 Proper firefighting techniques					Not Taken
Original Requirement 1					
Module 122					
4.4 Controlling the accidental release of gas					Not Taken
Original Requirement 1					
Module 131					
4.9 Job site protection					Not Taken
Original Requirement 1					
Module 401					
5.5 Flame ionization					Not Taken
Original Requirement 1					
Module 232					
Or Hands On 5.5 Flame ionization					
6.4 Pilot light operation					Not Taken
Original Requirement 1					
Module 311		2/5/2007	Taught By IAMU		
Original Requirement 2					
Module 324					
7.10 Reinforcing steel and plastic mains					Not Taken
Original Requirement 1					
Module 463					

Bedford Municipal Gas Co.

Jeremy Supinger Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
7.12 Plastic pipe joining (mechanical couplings)					Not Taken
Original Requirement 1					
Hands On 7.12 Plastic pipe joining (mechanical couplings)					
7.13 Recognition of defective material					Not Taken
Original Requirement 1					
Module 411					
Original Requirement 2					
Module 412		7/25/2011	Taught By IAMU		
Original Requirement 3					
Module 421		7/25/2011	Taught By IAMU		
7.16 Damage prevention					Not Taken
Original Requirement 1					
Module 462					
7.18 Replacing emergency valves					Not Taken
Original Requirement 1					
Module 441		7/25/2011	Taught By IAMU		
Original Requirement 2					
Module 511					
Or Hands On 12.3 Inspecting and maintaining key valves					
7.20 Tapping and stopping steel pipe 1" through 4"	7/30/2008		7/30/2008	7/30/2011	Expired
Original Requirement 1					
Hands On 7.20 Tapping and stopping steel pipe 1" through 4"		7/30/2008	Taught By IAMU		
7.2 Procedures for abandoning facilities					Not Taken
Original Requirement 1					
Module 471					
7.22 Tapping and stopping polyethylene pipe					Not Taken
Original Requirement 1					
Hands On 7.22 Tapping and stopping polyethylene pipe					
7.8 Steel and cast iron repair fittings					Not Taken
Original Requirement 1					
Module 461					
Original Requirement 2					
Hands On 7.8 Steel and cast iron repair fittings					
7.9 Maintaining steel and cast iron mains					Not Taken
Original Requirement 1					
Module 462					
8.3 Operating boring equipment	7/30/2008		7/30/2008	7/30/2011	Expired
Original Requirement 1					
Hands On 8.3 Operating boring equipment		7/30/2008	Taught By IAMU		

Bedford Municipal Gas Co.

Jeremy Supinger Operator Bedford

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
10.6 Holiday detection (coating inspection)					Not Taken
Original Requirement 1					
Module 431		7/25/2011	Taught By IAMU		
Original Requirement 2					
Hands On 10.6 Holiday detection (coating inspection)					
11.3 Testing odorant level					Not Taken
Original Requirement 1					
Module 251		1/12/2012	Taught By IAMU		
Original Requirement 2					
Hands On 11.3 Testing odorant level					
12.1 Operating valves (including emergency valves), regulators, and					Not Taken
Original Requirement 1					
Module 244		1/30/2007	Taught By IAMU		
Original Requirement 2					
Module 511					
Original Requirement 3					
Module 512					
12.2 Inspecting pressure regulating and limiting stations					Not Taken
Original Requirement 1					
Module 512					
Or Hands On 12.2 Inspecting pressure regulating and limiting stations					
12.3 Inspecting and maintaining key valves					Not Taken
Original Requirement 1					
Module 511					
Or Hands On 12.3 Inspecting and maintaining key valves					
12.4 System uprating					Not Taken
Original Requirement 1					
Module 521					