

IAMU OQ Past Due And Expired Training Report

Alton Municipal Utilities

Lee Van Klay Operator Alton

Tasks Required	Original Date	Prior Completion	Last Completed	Required By	Status
7.15 Steel pipe joining by mechanical couplings					Not Taken
Original Requirement 1					
Module 412		1/19/2012	Taught By IAMU		
Original Requirement 2					
Hands On 7.15 Steel pipe joining by mechanical couplings					
7.8 Steel and cast iron repair fittings					Not Taken
Original Requirement 1					
Module 461		1/19/2012	Taught By IAMU		
Original Requirement 2					
Hands On 7.8 Steel and cast iron repair fittings					
9.1 Metering					Not Taken
Original Requirement 1					
Hands On 9.1 Metering					
10.6 Holiday detection (coating inspection)					Not Taken
Original Requirement 1					
Module 431		1/19/2012	Taught By IAMU		
Original Requirement 2					
Hands On 10.6 Holiday detection (coating inspection)					
10.7 Painting and jacketing above ground facilities					Not Taken
Original Requirement 1					
Hands On 10.7 Painting and jacketing above ground facilities					